


# 7. Exploded View

UN36A (1Ø : 5, 7, 9kW)

\* Condenser Assembly Repaired Parts

Description	Location No.	Quantity
Condenser Assembly,Bending	554031	1
Tube Assembly,Manifold(Outdoor)	552115	1
Tube Assembly,Condenser(Out)	552113	1
Tube Assembly,Connector	352111A	1



**Thermistor Assembly,NTC**

Location No.	Thermistor Description	Housing Color
263230A	Water In/Water Out/PHE Out	Black
263230C	Pipe In	White
263230D	SUCTION	Green
263230E	DISCHA	Black
263230F	AIR	Yellow
263230G	MID-PIPE	Brown
263230H	CONDENSER_PIPE	Violet
263230J	VI_IN	White

**Service Bulletin**

Location No.	Service Description	Service Bulletin No.
158580	Pump, Water	DMZ202200153-01
HNMW11	Harness, Single	DMZ202200153-01
HNMW21	Harness, Multi	DMZ202200153-01